

September 29, 2020

Max-250K Connector Change Notification

Dear Valued Customer,

This letter is to inform you that Maxtec is in the process of making a change to a product you purchase. Due to a change in manufacturing, the connector (**RP12P27**) used with the Max-250k sensor (**R125P02-009 & R125P02-015**) will now have a new look. The connector change is only a visual (color) change and the function of the part will remain unaffected. In the past, we have used a clear-colored connector, but going forward, we will use a white-colored connector. We expect the change to be implemented over the next 2 months. As we make this change, we will have a mixed inventory of both the previous connector version and the new version. In order to get sensors to you as soon as possible, you may receive shipments that include both versions. Please see the photos below showing the visual difference. We apologize for any inconvenience this may cause. Please contact your Maxtec Sales Representative with any questions or concerns.

AFFECTED PRODUCT

- SENSOR, MAX-250K INTERNAL
- SENSOR, MAX-250K, W/PANDUIT CONN


Part Number: R125P02-015

Part Number: R125P02-009

Old



New



Old



New

www.maxtec.com

PHONE: 385.549.8000 · TOLL FREE: 866.4.Maxtec · FAX: 801.973.6090

2305 South 1070 West · Salt Lake City, UT · 84119 · USA